

Cisco MPP Firmware Maintenance

Cisco MPP Firmware Upgrade - Release 11.3.4 - **Updated**

Service Platforms:	Webex Carrier & Webex Calling VAR / SP
Markets:	NAMER, CANADA, EMEA, APAC, JAPAN
Maintenance Window: 11.3.4 Firmware Upgrade	CANADA - CA CDT: 29/Jun/21 08:00:00 PM EMEA - GMT: 29/Jun/21 08:00:00 PM NAMER - US ET: 29/Jun/21 08:00:00 PM JAPAN - JST: 30/Jun/21 09:00:00 PM APAC - AEST: 30/Jun/21 09:00:00 PM
Maintenance Window: ICE Enablement Webex Calling ONLY	DELAYED – Timing TBD CANADA – CA CDT: 1/July/21 08:00:00 PM EMEA – GMT: 8PM SP 8/July/21, VAR 15/July/21 NAMER – US ET: 8PM SP 19/July/21, VAR 23/July/21 JAPAN – JST 9 PM Non-KDDI 28/July/21 JAPAN – JST 9 PM KDDI 30/July/21 APAC – AEST 9PM SP 2/Aug/21, VAR 4/Aug/21
Information:	Cisco MPP Firmware Upgrade to 11.3.4
Affected Models:	Cisco MPP 6800, 7800, and 8800 Series
What's Changing:	MPP Firmware Upgrade 11.3.3 → 11.3.4
Upgrade Details: Webex Calling ONLY	<ol style="list-style-type: none"> Peripheral inventory reporting on Control Hub – WxC only <p>Peripheral inventory will allow admins to see KEM peripherals and digitally connected headsets connected to WxC deployed MPP phones in Control hub.</p> <ul style="list-style-type: none"> digital connection of headsets is available as follows: <ul style="list-style-type: none"> USB: MPP phones 8851/8861/8865/6871 RJ9 & RJ11 'Y' cable: 8811/8841/8845/8851/8861/8865 Headsets 52x, 53x and 56x support USB connection Headsets 56x support RJ9 & RJ11 'Y' cable connection KEM connectivity:

	<ul style="list-style-type: none"> ○ 8851/8861/8865 support BEKEM, CP-8800-A-KEM and CP-8800-V-KEM ○ 6851 supports CP-68KEM-3PCC <p style="text-align: center;">2. Media optimization using ICE – WxC only*</p> <p>ICE attempts to optimize the media path between two endpoints participating in a call. In WxC, an optimized call would allow media to bypass the hop to and back from the cloud improving latency, packet loss and overall media quality.</p> <p>*ICE Limitations</p> <p>CSCvy51309 → MPP software is not completing the ICE procedures when placing a call to L2SIP</p> <p>CSCvy56034 → ICE: Before complete transfer stay 12 min, one way video issue</p> <p>CSCvy58331 → ICE: Call Pickup with a video phone fails intermittently for a video call after ICE complete</p>
<p>End User Requirements:</p>	<p>WxC Carrier - Devices should be rebooted after the maintenance activity date.</p> <p>WxC VAR/SP – Devices will update automatically during their nightly re-sync window.</p>
<p>Documentation</p>	<p>MPP Release Notes</p> <ul style="list-style-type: none"> ● 6800 Release Notes ● 7800 Release Notes ● 8800 Release Notes