

Webex Calling - Cisco DECT DBS-110/210 Bases

Firmware Update from 5.1.1 to 5.1.2

Service Platforms:	Webex Calling Carrier
Markets:	NAMER, CANADA, EMEA, APAC
Maintenance Window:	CANADA - CA CST: 30/July/2024 10:00:00 PM EMEA - GMT: 30/July/2024 10:00:00 PM EUN - GMT: 30/July/2024 10:00:00 PM APAC - AEST 30/July/2024 10:00:00 PM NAMER – CST: 30/July/2024 10:00:00 PM
Information:	DECT Bases Firmare Upgrade from 5.1.1 to 5.12
Affected Models:	Cisco DECT DBS-110 and DBS-210 Bases
What's Changing:	<ul style="list-style-type: none">• Security Patches• Voice Vlan <<IMPORTANT – PLEASE READ>> <p><u><i>Starting with release 5.1.2, Cisco DECT bases will support the Voice VLAN feature. This release is slated for deployment around July 2024. To prevent the bases from entering the Voice VLAN inadvertently after the upgrade to release 5.1.2, it is crucial to ensure that Voice VLAN is disabled on all switch ports connected to Cisco DECT bases before July 2024.</i></u></p> <p><u><i>Upon completing the upgrade to release 5.1.2, customers interested in utilizing the Voice VLAN can enable it on their switches and adjust their network configurations to facilitate communication between the bases and WxC.</i></u></p>

Bug Fix:	<ul style="list-style-type: none"> • CSCwd11394 Cannot login to DBS210 web GUI with correct Admin password • CSCwd11388 All handsets deregister after performing any handset related operation from Control Hub • CSCvz61849 Handset can not be associated with Alarm profile through config file • CSCwd11390 No Geolocation header for emergency calls • CSCwd25173 Feature pack is using lot of DECT resources • CSCwd25148 Leak of Call Instances if no Response to Endpoint Request • CSCwd25158 ROS2 mail queue full from Mac Interrupt observed in Autotest • CSCwd25168 Update SCA icons are using a lot of DECT resources • CSCwd25133 Full System test showed very slow FWU updates and UDP packet loss for base stations • CSCwa93524 <Login_User_ID> needs to have a per line scope • CSCwa15271 Callog related parameters should be removed from the web UI and XML tokens • CSCwa59141 CIAM: mbed-tls 2.23.0 upgrade to mbed-tls 2.28.0 • CSCwd25122 Restrict admin web UI login to a single active session by closing the previous session • CSCwi76847 DECT handset unresponsive after receiving a voicemail notification
Upgrade Details:	Changes will happen during the aforementioned maintenance windows per region.
End User Requirements:	Verify Voice VLAN Settings and make sure that the Voice VLAN is disabled prior to firmware upgrade.