

Cisco ATA Endpoint Maintenance

Cisco ATA 191/192 - Firmware Upgrade 11.1.0MPP0402.002 ES

Service Platforms:	Webex Calling Carrier/SP/VAR
Markets:	NAMER, CANADA, EMEA, APAC, JAPAN
Maintenance Window:	NAMER - US ET: 02/15/2021 10:00:00 PM CANADA - US ET: 02/15/2021 10:00:00 PM EMEA - GMT: 02/17/2021 10:00:00 PM APAC - AEST: 03/04/2021 01:00:00 AM- DATE CHANGED JAPAN - GMT: 02/18/2021 02:00:00 PM
Information:	Cisco ATA 191/192 Firmware Upgrade to 11.1.0MPP0402.002 ES
Affected Models:	Cisco ATA 191/192 with Multiplatform Firmware
What's Changing:	MPP Firmware Upgrade 11.1.0MSR4 --> 11.1.0MPP0402.002 ES
Upgrade Details:	Firmware 11.1.0MPP0402.002 ES is a Service Release that includes bug fixes and general improvements. Specifically these issues are being addressed. CSCvx05785: MPP ATA19x - No audio on either side due to RTP start failure CSCvx05795: MPP ATA19X cannot make call for some time
End User Requirements:	WxC Carrier - Devices should be rebooted after the maintenance activity date to download the new firmware. The device will reboot as a result of the firmware upgrade process. WxC VAR/SP – Devices will update automatically during their nightly re-sync window. The device will reboot as a result of the firmware upgrade process.

